KUCHING CONTROL ZONE



CHANGES : CHANGE COORDINATES FOR KUCHING DVOR/DME.